Following updated is only available to new vocoder version; please check menu-utilities-radio info-versions-D013.009, and if you radio is D013 version, you can use this updated firmware and if you radio is D002 or D003 version, please don't use this firmware, or it will cause radios reboot all the time and please kindly note that is firmware is available for MD-390 with GPS and MD-380G with GPS and new vocoder of D013 version

Firmware version : TYT-Vocoder-MD390-S13.20.bin
Programming software: V1.36

1、 Address the issue that GPS information is not shown when using with repeater
2、 Address the issue that radio will be frozen when using with repeater
3、 adding 1750Hz tone
4、 Solve the problem of blank display
5、 Adding mid bandwidth as 20K

Press side key 1 and PTT key to turn on the radio, the indicator blinks and open upgraded software

And then write upgraded file named Upgraded software for scanning function into radio, the radio will be upgraded as following:

下载软件

打开

查找范围(I): Upgraded softare for scanni

文件名(N): Upgraded software for scanning function
文件类型(T): (*.bin)

☐ 以只读方式打开(R)

打开(O)
取消

Open ID File   Read ID   Active ID

正在升级软件.......

BOOT Download

Open BOOT File   Down BOOT File

User Program

C:\Users\Administrator\Desktop\MD-380\Upgraded softare for sca

Open Update File   Open Code File   Download Update File

ID

Open ID File   Read ID   Active ID