

when you open the the OTA program and scanbr/edr
Do you see the ELET_
if you touch the ELET it should float in the OTA program
if yes

then you need to find the V0030 file
the file you should look for

B707_Audio_AGHF_ET12QX-V10030

If yes

You should see the Path, in the Patch File Path line.


If you see the file, then click upgrade and it will write ok

Make sure the battery is charged in the PTT

Make sure the PTT is connected to the radio, You know Blue Color P

It may show BLUE, but still not connected.

Test the PTT to see if radio transmits.



Good Luck,

Can you imagine how many people are going to be asking for help, if a document is not Chrystal clear.

I have 9.0

You have to copy both folders in the Phone directory "Download Folder"

Do not copy V10030 FW(for BT in radio) folder **in the SD card**


V10030 FW(for BT in radio) has to be copied to the phone download folder

First things first.


Radio and PTT must be paired and connected, before you do anything.




Next, connect phone with USB and open computer.




Then double click Android Phone




Then double click Phone





Double click Download Folder.





This is where you copy the folders. Update Tool and V10030 FW














Click to Install.

9:14



OTA

Do you want to install an update to this existing application? Your existing data will not be lost. It does not require any special access.

Cancel

Install



9:14



OTA





App installed.

Done


Open










Look in the download folder, V10030 FW










After the Firmware is finished. Disconnect.

Close Program and shut off the radio and turn it back on.

Then go to settings to check the version.



That is the best I can do on a such short time that I have.